JACKSON PLAYGROUND

1645 17TH STREET SAN FRANCISCO, CA 94107

PARCEL APN: 3981 / 001

PUBLIC PROJECT APPLICATION FOR ENVIRONMENTAL REVIEW

06/10/2020 REVISED 03/18/2022

AERIAL PERSPECTIVE FROM NW CORNER



SHEET INDEX

GENERAL

G1.00 **COVER SHEET** EXISTING VS. PROPOSED AERIAL PERSPECTIVES G1.01 SITE L0.00 **EXISTING SITE PLAN** L0.01 **DEMOLITION PLAN** OVERALL SITE PLAN L0.02 TREE PROTECTION PLAN L0.03 L0.04 PROPOSED TREES PROPOSED TREES PALETTE L0.05 L0.06 SITE DISTURBANCE PLAN SITE VIGNETTES L1.01 PARK ENLARGEMENT PLAN - NORTH L1.02 PARK ENLARGEMENT PLAN - SOUTH L1.03 17TH ST ENLARGEMENT PLANS L1.04 L1.05 ARKANSAS ST ENLARGEMENT PLANS MARIPOSA ST ENLARGEMENT PLANS L1.06

MATERIALS PLAN

MATERIALS PALETTE

CAROLINA ST ENLARGEMENT PLANS

SITE BOUNDARY EXPRESSION

ARCHITECTURE
SEE SHEET A0.00 COVER SHEET FOR ARCHITECTURAL DRAWING INDEX

URBAN CONTEXT PLAN



PROJECT DIRECTORY

OWNER CITY OF SAN FRANCISCO RECREATION & PARKS DEPARTMENT

DEPUTY DIRECTOR
STACY BRADLEY
30 VAN NESS AVE., 5TH FLOOR
SAN FRANCISCO, CA 94102
Telephone: 415.823.9120
Email: stacy.bradley@sfgov.org

CLIENT FRIENDS OF JACKSON PARK EXECUTIVE DIRECTOR

JUDE DECKENBACH Telephone: 415.786.2427

Email: judedeckenbach@gmail.com

LANDSCAPE ARCHITECT (PRIME) FLETCHER STUDIO

2325 3RD STREET, SUITE 413, FLR 4 SAN FRANCISCO, CALIFORNIA 94107 Telephone: 415.431.7878

Email: lewald@fletcherstudio.com

ARCHITECT JACKSON LILES ARCHITECTURE

2325 3RD STREET, SUITE 206, FLR 2 SAN FRANCISCO, CA 94107 Telephone: 415.621.1799 Email: brian@jacksonliles.com CIVIL ENGINEER
SANDIS ENGINEERS

636 9TH STREET OAKLAND, CA 94607 Telephone: 510.873.8866

Email: mkuykendall@sandis.net

SPORTS FIELD DESIGN VERDE DESIGN INC.

VERDE DESIGN INC. 2455 THE ALAMEDA, SUITE #200 SANTA CLARA, CA 94050

Telephone: 408.850.3411

Email: mark@verdedesigninc.com

COST ESTIMATOR M LEE CORPORATION

601 MONTGOMERY ST, STE 2040 SAN FRANCISCO, CA 94111 Telephone: 415.693.0236 Email: flee@mleecorp.com



L1.07

L1.08


L1.09

L1.10










COVER SHEET

03/18/2022

G1.00



EXISTING SITE - NW CORNER




PROPOSED SITE - NW CORNER










EXISTING VS. PROPOSED-AERIAL PERSPECTIVES 03/18/2022

G1.01















EXISTING SITE PLAN


1" = 50'
03/18/2022 **LO.00**












L0.02





LANDSCAPE LEGEND							
SYMBOL QTY.		BOTANNICAL NAME / COMMON NAME	SIZE				
PA /	5	(E) PLATANUS X ACERIFOLIA / LONDON PLANE TREE	1				
OE /	2	(E) OLEA EUROPAEA / OLIVE TREE	1				
(T)	1	TRANSPLANTED OLEA EUROPAEA / OLIVE TREE					
	16 CASSIA LEPTOPHYLLA / GOLD MEDALLION TREE						
	11	GINKGO BILOBA 'AUTUMN GOLD' / AUTUMN GOLD MAIDENHAIR TREE					
	13	LAGUNARIA PATERSONII / PRIMROSE TREE	24" BOX				
	10	LOPHOSTEMON CONFERTUS / BRISBANE BOX					
$oxed{\cdot}$) MAGNOLIA GRANDIFLORA 'ST. MARY' / SAINT MARY SOUTHERN MAGNOLIA		24" BOX				
	27	OLEA EUROPAEA 'SWAN HILL' / SWAN HILL FRUITLESS OLIVE	24" BOX				
	7	PLATUNUS ACERIFOLIA 'COLUMBIA' / COLUMBIA SYCAMORE	24" BOX				
	7 PRUNUS SERRULATA 'SNOW FOUNTAINS' / WEEPING FLOWERING CHERRY		24" BOX				

NORTH









Jackson Liles
ARCHITECTURE



PROPOSED TREES

1" = 50' 03/18/2022





TOTAL SITE DISTURBANCE AREA SUMMARY

DESCRIPTION AREA (IN SQ. FT.)

TOTAL AREA OF DISTURBANCE 218,730

- TOTAL OFF-SITE DISTURBANCE AREA 26,720

- TOTAL ON-SITE DISTURBANCE AREA 192,010

OFF-SITE DISTURBANCE AREA SUMMARY				
DESCRIPTION	AREA (IN SQ. FT.)			
1	TOTAL OFF-SITE DISTURBANCE (INCLUDING CONC. PAVING, SPECIAL PAVING, PLANTING & TREE PITS, BULB-OUTS AT CORNERS)	26,720		

ON-SITE DISTURBANCE AREA SUMMARY							
DESCRIPTION	AREA (IN SQ. FT.)						
TOTAL ON-SIT	192,010						
TOTAL ON-SITE DISTURBANCE AREA		192,010					
2	TOTAL STRUCTURES	6,576					
	- CLUBHOUSE	4,746					
	- ADDITION	1,830					
3	MULTI-PURPOSE COURTS	10,210					
4	BALL FIELDS (FINES, FIELD & DUGOUTS)	125,340					
+++++++++++++++++++++++++++++++++++++++	NATURAL GRASS	9,310					
6	PLAY AREA SURFACING (7-12 PLAY AREA)	6,300					
	PLAY AREA SURFACING (0-6 PLAY AREA), INCLUDING SAND BOX PLAY AREA	2,700					
7	HARDSCAPE (CONCRETE, PAVERS, DG, ETC.)	19,820					
	REGULAR PLANTING AREA	11,484					
8	STORMWATER PLANTING AREA (APPROX.)	270					

PRELIMINARY EARTHWORK QUANTITIES

CUT 13,300 CY FILL 1,000 CY BALANCE: 12,300 CY EXPORT

THE EARTHWORK QUANTITIES SHOWN ARE PROVIDED AS ESTIMATES ONLY, SIGNIFICANT CHANGES ARE LIKELY TO OCCUR AS THE PROJECT DESIGN IS FULLY DEVELOPED.



1" = 50'


L0.06



- **BALLFIELD SEATING AREA**
- CONC RETAINING WALL
- RAMP & ANODIZED ALUMINUM HANDRAILS
- SPECTATOR SEATING, 36"W TYP. X 18"H, THERMALLY **MODIFIED WOOD**




- **BULB-OUT ENTRANCE PLAZA**
- INTEGRAL COLOR CONC. PAVERS 8|L1.09
- CITY STD. CONC PAVING
- TAPERED CIP CONC. SEAT WALL, 24"W MIN. X 18" H
- FREESTANDING HALF-BLOCK CMU WALLS, BURNISHED FINISH WITH MURALS ON OPPOSITE SIDES (HEIGHT VARIES 8'-14')
- 5 CHAINLINK ENTRY GATE



- **PLAY AREA**
- POURED-IN-PLACE RUBBER SURFACING, PATTERN TBD 7|L1.09
- SYNTHETIC TURF PLAY AREA SURFACING
- CONC. SEAT WALL, 24"W X 18"H, LENGTH VARIES
- 'NATURAL' ROBINIA PLAY ELEMENTS, EXACT DESIGN
- TBD WITH FURTHER COMMUNITY INPUT
- THERMALLY MODIFIED WOOD FENCE
- SAND PLAY AREA



- **ELEVATED OPEN SPACE**
- SYNTHETIC TURF PLAY AREA SURFACING
- DUGOUT W/ SCULPTURAL ALUMINUM ROOF, STANDING SEAM W/ SLOT OPENINGS
- SCULPTURAL CONC STEPS, 24" W TREADS TYP. WITH **SEAT WALL EXTENSIONS**
- ANODIZED ALUMINUM HANDRAILS, TYP.
- 'MULTIPLICITY' PICNIC TABLES & BENCHES, THERMALLY MODIFIED WOOD, 8' W X 7'-10" L
- 2|L1.09



- **AMPHITHEATER SEATING**
- SCULPTURAL SEATING ELEMENTS, THERMALLY MODIFIED WOOD, HOLLOW WITH PT FRAMING
- SAND-SET CONC. UNIT PAVERS W/ METAL EDGING | 5|L1.09
- NATURAL GRASS
- ANODIZED ALUMINUM HANDRAILS, TYP.
- WIDE CONCRETE STEPS, 24" W TREADS



MULTI-PURPOSE COURT

- ACRYLIC SPORTS COURTS SURFACING (WITH **CUSHIONING, ON CONCRETE SLAB)**
- THERMORY WOOD TRAVERSE WALLS WITH CLIMBING HANDHOLDS
- FREESTANDING HALF-BLOCK CMU WALLS, BURNISHED FINISH WITH MURALS ON OPPOSITE SIDES (HEIGHT VARIES 8'-14')
- CLUBHOUSE ADDITION FACADE, MURAL BY LOCAL ARTIST TBD
- "BLACK-TOP" STYLE GAMES (FOUR SQUARE, HOPSCOTCH, ETC.), ACRYLIC SURFACING ON CONCRETE SLAB








Jackson Liles ARCHITECTURE



SITE VIGNETTES

03/18/2022

L1.01






- 1 PASSIVE OPEN SPACE
- 2 PLAY AREA (AGES 7-12)
- PLAY AREA (AGES 0-6), INCLUDING SAND PLAY AREA
- 4 BASEBALL FIELD
- 5 DUGOUT
- 6 CLUBHOUSE (RELOCATED)
- 7 SEAT WALL, TYP.
- SCULPTURAL CONCRETE STEPS
- PICNIC AREA
- 10 SCULPTURAL FIELD FENCE
- 1 ENTRY PLAZA
- RELOCATED SFRPD PARK SIGN










PARK ENLARGEMENT PLAN - NORTH AS SHOWN
03/18/2022
L1.02



SITE LEGEND


- 1 PASSIVE OPEN SPACE
- 2 BASEBALL FIELD
- 3 CLUBHOUSE (RELOCATED)
- CLUBHOUSE STAGE, S.A.D.
- CLUBHOUSE ADDITION, S.A.D.
- AMPHITHEATER SEATING
- 7 ELEVATED OPEN SPACE
 - MULTI-PURPOSE COURT: 1 BASKETBALL COURT, 1 FUTSAL COURT, 2 PICKLEBALL COURTS
 - SEAT WALL, TYP.
 - SCULPTURAL CONCRETE STEPS
- PICNIC AREA
- SCULPTURAL FIELD FENCE
- TRAVERSE WALL
- 14 MURAL
- ENTRY PLAZA
- RELOCATED FLAGPOLE
- FREESTANDING WALLS
- COURT FENCE
- TENNIS PRACTICE BACKBOARD













PARK ENLARGEMENT PLAN - SOUTH


1" = 20'-0" 03/18/2022 L1.03








17TH ST ENLARGEMENT PLANS 03/18/2022 L1.04











ARKANSAS ST ENLARGEMENT PLANS

SITE LEGEND

2

3

1 SOFTBALL FIELD

DUGOUT


PICNIC AREA


FIELD MAINTENANCE ACCESS
TRASH CAN 4|L1.09

DRINKING FOUNTAIN 1|L1.09
PLAZA AREA (SPECIAL PAVING)

1" = 20'-0" 03/18/2022

L1.05





Jackson Liles

ARCHITECTURE

SITE LEGEND

5

KEY PLAN

1 STREETSCAPE

3 STREETLIGHT, TYP.
4 PLAZA

SEAT WALL, TYP. 6 PASS-THROUGH


1" = 20'-0"

03/18/2022

L1.07

CAROLINA ST ENLARGEMENT PLANS

2 BIKE RACK, TYP. 3|L1.09





9 COURTESY STRIP MFR: ACKERSTONE COLOR: GRAPHITE SIZE: 4" X 18" PATTERN: STACKED BOND



INTEGRAL COLOR CONC. PAVER
DEPTH: 4" CONC. SECTION W/ 6"
DEPTH AGG. BASE
COLOR: 50% GRAPHITE, 50% GRAY
NOTE: BASE AND COMPACTION T.B.D.
PER GEOTECH FINDINGS.



POURED-IN-PLACE RUBBER SURFACING MFR: SURFACE AMERICA COLOR/PATTERN: TBD



STABILIZED DECOMPOSED GRANITE PAVING W/ EDGING COLOR: TAN



SAND-SET CONC. UNIT PAVERS W/ METAL EDGING COLOR: 50% ALMOND, 50% LINEN SIZE: 4" W X 24" L FINISH: GROUND-FACE



TRASH/ RECYCLING RECEPTACLE
MFR: QCP CONCRETE 'SEDONA'
COLOR: FRENCH GRAY
SURFACE MOUNT



'WELLE' CIRCULAR BIKE RACK, CITY STD.



'MULTIPLICITY' THERMORY
RECTANGULAR PICNIC
TABLE W/ (2) LONG BENCHES PER
TABLE. METAL FRAME. SURFACE
MOUNT.
REGULAR TABLE SIZE: 95" L X 35" W X
29" H
BENCH SIZE: 95" L X 23" W X 18" H
PROVIDE SHORTER BENCHES TO
MAKE TABLE ACCESSIBLE WHERE

SHOWN




DRINKING FOUNTAIN 10145SMSS W/BOTTLE FILLER
AND (2) SPOUTS, HI & LO FOR ADA COMPLIANCE.
HOSE BIBB ATTACHMENT W/LOCK & DOOR.
MFR: MOST DEPENDABLE FOUNTAINS COLOR: GRAY
NOTES: PROVIDE PET FOUNTAIN ATTACHMENT FOR FIXTURE @ DOG RUN







Jackson Liles
ARCHITECTURE



MATERIALS PALETTE

N/A 03/18/2022

L1.09







HISTORICAL REGISTRATION




PATHWA

SITE BOUNDARY LEGEND

- ---- SEAT WALLS & FENCING
- ---- HISTORICAL REGISTRATION
- PATHWAY EDGE












Jackson Liles
ARCHITECTURE



SITE BOUNDARY EXPRESSION

1" = 50' 03/18/2022

NORTH

L1.10

JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



DRAWING INDEX

DIVATION	IO INDEX					
GENERA	AL .	PROPOS	SED PROJECT			
A0.00	COVER SHEET	A3.01	PROPOSED FLOOR PLAN	A6.03	WINDOW SCHEDULE - NEW	
A0.01	KEY PRECEDENT	A3.02	PROPOSED ROOF PLAN	A6.04	WINDOW LEGEND - EXISTING & NEW	
A0.02	MATERIAL COMPATIBILITY	A4.01	WEST ELEVATIONS - EXISTING & PROPOSED	A6.05	STOREFRONT LEGEND - NEW	
EXISTING CONDITIONS		A4.02	NORTH ELEVATIONS - EXISTING & PROPOSED	A6.06	EXTERIOR DOOR SCHEDULE - EXISTING & NEW	
		A4.03a	SOUTH ELEVATIONS - EXISTING & PROPOSED	A6.07	EXTERIOR DOOR LEGEND - EXISTING & NEW	
A0.11	SITE PHOTOS - EXISTING	A4.03b	SOUTH ELEVATIONS - PROPOSED	A6.08	GLAZED FOLDING DOOR PRECEDENT	
A0.12	SITE PHOTOS - NEIGHBORING ELEVATIONS	A4.04	EAST ELEVATIONS - EXISTING & PROPOSED	A6.09	GLAZED FOLDING DOOR DETAILS	
A0.13	EXISTING CLUBHOUSE PHOTOS - EXTERIOR	ODENIN	OO EVICTING A PROPOSER			
A0.14	A0.14 EXISTING CLUBHOUSE PHOTOS - EXTERIOR		OPENINGS - EXISTING & PROPOSED		RENDERINGS	
A0.15	EXISTING CLUBHOUSE PHOTOS - INTERIOR	A4.11	PROPOSED BUILDING SECTIONS	A7.01	PERSPECTIVE VIEW FROM NORTHWEST	
A1.01	EXISTING CLUBHOUSE - FLOOR PLAN	A5.11	EXISTING WINDOW & DOOR KEY PLAN - LEVEL 1	A7.02	PERSPECTIVE VIEW FROM NORTHWEST	
A1.02	EXISTING CLUBHOUSE - ELEVATIONS	A5.12	EXISTING WINDOW KEY PLAN - CLERESTORY	A7.03	PERSPECTIVE VIEW FROM WEST	
A1.03	EXISTING CLUBHOUSE - ELEVATIONS	A5.13	EXISTING WINDOW & DOOR KEY - ELEVATIONS	A7.04	PERSPECTIVE VIEW FROM SOUTHWEST	
A1.04	EXISTING CLUBHOUSE - SECTIONS	A5.21	PROPOSED WINDOW & DOOR KEY PLAN - LEVEL 1	A7.05	PERSPECTIVE VIEW FROM SOUTH	
DEMOLITION & RELOCATION		A5.22	PROPOSED WINDOW KEY PLAN - CLERESTORY	A7.06	PERSPECTIVE VIEW FROM SOUTHEAST	
		A5.23	PROPOSED WINDOW & DOOR KEY - ELEVATIONS	A7.07	PERSPECTIVE VIEW FROM EAST	
A2.01	CLUBHOUSE RELOCATION PLAN	A5.24	PROPOSED WINDOW & DOOR KEY - ELEVATIONS &	A7.08	PERSPECTIVE VIEW FROM NORTHEAST	
A2.02	CLUBHOUSE RELOCATION DEMOLITION PLAN		SECTION	A7.09	PERSPECTIVE VIEW FROM NORTH	
A2.03	CLUBHOUSE RENOVATION DEMOLITION PLAN	A6.01	WINDOW SCHEDULE - EXISTING - LEVEL 1			
		A6.02	WINDOW SCHEDULE - EXISTING - CLERESTORY			

Jackson Liles

ARCHITECTURE

JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

12" = 1'-0"

03/18/2022

COVER SHEET

A0.00

KEY PRECEDENT

PALEGA ADDITION: Recreation & Parks Project in San Francisco

Challenge - Addition proximate to multi- tiered historic building massing

Solution - Addition to mediate between levels, allowing full view of lower level wall to roof transition, with roof fitting in between upper and lower tiers.

Challenge - Create new multi-use space connected to exterior play yard

Solution - Utilize mix of steel and glaze in tradition of park pavilions to define contemporary space in respective approach to existing historic structure.

Challenge - Relate to and deferential to existing historic structure

Solution - Use steel frame and glass to create a lighter sense to addition, affirming the historic buildings wieght and solidity while relating to adjacent park activities.



Exterior view of the Palega Recreation Center



Interior view of the recreation center



Interior view of the recreation center



1 WEST ELEVATION 3/32" = 1'-0"







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

As indicated 03/18/2022


KEY PRECEDENT

A0.01

MATERIAL COMPATIBILITY







Board form concrete material will be used in outdoor spaces and work to knit the building into Landscape, thus deferring to Historic building



Stage door complements historic aesthetic & creates programmatic connection between interior and exterior spaces



Storefront glazing provides simple transparency to allow Historic Building to be seen from all sides







SITE PHOTOS - EXISTING







2 SITE PHOTO 2

3 SITE PHOTO 3



4 SITE PHOTO 4

1 SITE PHOTO 1



5 SITE PHOTO 5




6 SITE PHOTO 6









SITE PHOTOS -EXISTING 03/18/2022 A0.11

SITE PHOTOS - NEIGHBORING ELEVATIONS



1 17TH STREET ELEVATION



ARKANSAS STREET ELEVATION



3 MARIPOSA STREET ELEVATION




4 CAROLINA STREET ELEVATION







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



SITE PHOTOS -NEIGHBORING ELEVATIONS 1/8" = 1'-0" 03/18/2022 A0.12

EXISTING CLUBHOUSE PHOTOS - EXTERIOR









(E) CLUBHOUSE EXTERIOR - EAST

(3) EXAMPLE OF PLEXIGLASS INFILL AT WINDOWS











(E) CLUBHOUSE EXTERIOR - NORTH







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



EXISTING CLUBHOUSE PHOTOS - EXTERIOR


03/18/2022 A0.13

EXISTING CLUBHOUSE PHOTOS - EXTERIOR











(E) CLUBHOUSE EXTERIOR - WEST











(E) CLUBHOUSE EXTERIOR - SOUTH








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



EXISTING CLUBHOUSE PHOTOS - EXTERIOR

EXISTING CLUBHOUSE PHOTOS - INTERIOR







(E) CLUBHOUSE INTERIOR PHOTO 2



(E) CLUBHOUSE INTERIOR PHOTO 3



(E) CLUBHOUSE INTERIOR PHOTO 4



(E) CLUBHOUSE INTERIOR PHOTO 5




(E) CLUBHOUSE INTERIOR PHOTO 6








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



EXISTING CLUBHOUSE PHOTOS - INTERIOR

03/18/2022 A0.15

EXISTING CLUBHOUSE - FLOOR PLAN





- 1 T&G WOOD FLOORING OVER WOOD FRAMING, CRAWL SPACE BENEATH
- 2 RAISED TREX DECK OVER WOOD FRAMING, CRAWL SPACE BELOW
- (3) CONC STAIR AND LANDING
- (4) CONC LOW WALL
- (5) WOOD STAIR
- 6 CONC PLANTERS AND LOW WALL AT EDGE OF DECK
- 7) RAISED STAGE W/ STORAGE BELOW
- (8) PAINTED WOOD PANELING AND TRIM AT MULTI-PURPOSE ROOM WALLS AND CEILING

NOTE: SEE A5.11 & A5.12 FOR EXISTING WINDOW & DOOR KEY PLAN








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION




EXISTING CLUBHOUSE - FLOOR PLAN 1/16" = 1'-0" 03/18/2022 A1.01

EXISTING CLUBHOUSE - ELEVATIONS



1 EXISTING CLUBHOUSE - NORTH ELEVATION 3/32" = 1'-0"



SHEET NOTES

- (1) WOOD WINDOW W/ WOOD TRIM
- (2) HOLLOW MTL DOOR W/ MTL TRIM
- 3 RAISED TREX DECK & LOW CEMENT PLASTER WALLS
- 4 EXTERIOR FINISH PAINTED FLUSH (T&G) WOOD SIDING
- (5) EXTERIOR WOOD TRIM, TYP
- (6) GA SHT MTL CAP FLASHING AT PARAPET
- (7) COMPOSITION SHINGLE ROOFING
- (8) INFILL PANEL AT OPENING
- (9) INFILL PANEL W/ TILE MURAL
- (10) SECURITY GRILLE AT ALL LEVEL 1 WINDOWS
- (11) METAL DOOR
- (12) CHIMNEY


NOTE: SEE A5.13 FOR EXISTING WINDOW & DOOR KEY ELEVATIONS








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION




EXISTING CLUBHOUSE
- ELEVATIONS

EXISTING CLUBHOUSE - ELEVATIONS



1 EXISTING CLUBHOUSE - SOUTH ELEVATION 3/32" = 1'-0"



EXISTING CLUBHOUSE - EAST ELEVATION 3/32" = 1'-0"

FLETCHERBTUDIO





JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

SHEET NOTES

- 1) WOOD WINDOW W/ WOOD TRIM
- (2) HOLLOW MTL DOOR W/ MTL TRIM
- 3 RAISED TREX DECK & LOW CEMENT PLASTER WALLS
- 4 EXTERIOR FINISH PAINTED FLUSH (T&G) WOOD SIDING
- (5) EXTERIOR WOOD TRIM, TYP
- (6) GA SHT MTL CAP FLASHING AT PARAPET
- (7) COMPOSITION SHINGLE ROOFING
- (8) INFILL PANEL AT OPENING
- (9) INFILL PANEL W/ TILE MURAL
- (10) SECURITY GRILLE AT ALL LEVEL 1 WINDOWS
- (11) METAL DOOR
- (12) CHIMNEY

NOTE: SEE A5.13 FOR EXISTING WINDOW & DOOR KEY ELEVATIONS




EXISTING CLUBHOUSE
- ELEVATIONS

As indicated

03/18/2022

EXISTING CLUBHOUSE - SECTIONS



EXISTING CLUBHOUSE - SECTION 3/32" = 1'-0"


EXISTING CLUBHOUSE - SECTION

3/32" = 1'-0"

(5) TYP (6)TYP **EXISTING** CLUBHOUSE F.F. (7)


Jackson Liles ARCHITECTURE

JACKSON PARK CLUBHOUSE **RELOCATION & ADDITION**



EXISTING CLUBHOUSE - SECTIONS


As indicated 03/18/2022 A1.04



SHEET NOTES

- (1) PAINTED WOOD PANELING & TRIM, TYP
- (2) RAISED WOOD STAGE
- (3) STORAGE UNDER STAGE
- 4 PAINTED WOOD PANELING & TRIM W/ TILE WAINSCOT AT RESTROOMS, TYP
- (5) WINDOW W/ WOOD TRIM
- (6) WOOD DOOR W/ WOOD TRIM
- (7) CRAWL SPACE
- (8) RAISED WOOD DECK AND LOW WALLS

CLUBHOUSE RELOCATION PLAN



GENERAL NOTES

- A. BACKSTOP, BLEACHERS, LIGHT POLES, FENCING, ETC. TO BE DEMOLISHED IN ADVANCE OF BUILDING RELOCATION
- B. REFER TO RELOCATION REPORT FOR SPECIFIC ACTIVITIES AND REQUIREMENTS ASSOCIATED WITH BUILDING RELOCATION



SITE PLAN - CLUBHOUSE RELOCATION PLAN


1" = 60'-0"








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



CLUBHOUSE RELOCATION PLAN 1" = 60'-0"
03/18/2022

A2.01

CLUBHOUSE RELOCATION DEMOLITION PLAN (PHASE 1 DEMOLITION)





- A. THIS DEMOLITION IS TO OCCUR IN PREPARATION FOR BUILDING RELOCATION
- B. PREPARE (E) CLUBHOUSE FOR RELOCATION
- C. PROTECT ALL COMPONENTS OF THE BUILDING WHICH ARE TO REMAIN & BE RENOVATED, INCLUDING EXTERIOR FINISHES, DOORS & WINDOWS, AND OTHER ARCHITECTURAL ELEMENTS
- D. DISCONNECT ALL UTILITIES AND REMOVE PIPING, CONDUITS, WIRING, ETC. THAT EXTEND UNDER THE BUILDING OR BEYOND THE BUILDNG ENVELOPE
- E. RETAIN INTERIOR PARTITIONS SLATED FOR FUTURE DEMOLITION AS NEEDED FOR BRACING
- F. COMPLETE DEMOLITION OF INTERIOR CABINETRY, HVAC AND PLUMBING EQUIPMENT, ELECTRICAL TRANSFORMERS AND MAIN PANELS, WALL MOUNTED ITEMS, AND ANY OTHER ITEMS INDICATED ON THE DRAWINGS

DEMOLITION NOTES


- 1 REMOVE (E) DECK, INCLUDING DECK STRUCTURE, STAIRS, RAMPS, WALLS, & RAILINGS
- (2) REMOVE (E) EXTERIOR STAIR & RAILINGS
- 3 PARTIAL DEMOLITION OF EXISTING STRUCTURE UNDER THE BUILDING MAY BE REQUIRED TO INSTALL STEEL SUPPORT BEAMS FOR BUILDING RELOCATION
- 4 REMOVE ELECTRICAL TRANSFORMERS, PANELS AND ALL EQUIPMENT LOCATED IN THE CAGED AREA ON THE STAGE
- 5 REMOVE FURNACE, MECHANICAL EQUIP AND PRIMARY DUCTWORK













CLUBHOUSE RELOCATION DEMOLITION PLAN



CLUBHOUSE RENOVATION DEMOLITION PLAN (PHASE 2 DEMOLITION)



1 DEMOLITION PLAN 1/16" = 1'-0"









JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

GENERAL NOTES


- A. THIS DEMOLITION IS TO OCCUR AFTER THE BUILDING HAS BEEN RELOCATED.
- B. AFTER BUILDING IS RELOCATED TO NEW LOCATION IT WILL BE RAISED ON CRIBBING SO THE NEW FOUNDATION CAN BE BUILT BELOW THE BUILDING
- C. WHEN FOUNDATION IS COMPLETE, LOWER THE CLUBHOUSE SUCH THAT IT IS BROUGHT DOWN TO GRADE ON A NEW FOUNDATION WITH CRAWL SPACE
- D. RETAIN & PROTECT INTERIOR TRIM FOR ALL WINDOWS & DOORS TO REMAIN
- E. REMOVE (E) INTERIOR WALL AND CEILING FINISHES.
- F. REMOVE (E) PLUMBING, LIGHT, AND MECHANICAL FIXTURES AND OTHER COMPONENTS
- G. REMOVE BRICK CHIMNEYS
- H. REMOVE ALL ROOFING & BUILDING PAPER

DEMOLITION NOTES

- 1 REMOVE (E) WOOD PANELING AT ALL INTERIOR WALLS, TYP
- (2) REMOVE (E) WOOD PANELING AT ALL CEILINGS, TYP
- 3 REMOVE (E) RAISED STAGE FLOOR (STAGE SITS OVER THE (E) SUBFLOOR)
- (4) REMOVE (E) WALL
- (5) NOT USED
- (6) NOT USED
- 7) REMOVE (E) MTL DOOR AND FRAME
- 8 REMOVE INFILL PANEL INSTALLED IN 1959-61
- 9) REMOVE PORTION OF WALL FOR (N) OPENING
 - 10) REMOVE PORTION OF WALL FOR (N) DOOR



1/16" = 1'-0"



SHEET NOTES

- (E) EXTERIOR WALL OF RELOCATED CLUBHOUSE TO REMAIN AND BECOME INTERIOR SURFACE OF ADDITION
- (2) (N) CURTAIN WALL TO PROVIDE TRANSPARENCY TO SEE FULL EXTERIOR OF CLUBHOUSE
- (N) HORIZONTAL BOARD FORM CONCRETE WALL, CLEAR MATTE FINISH
- (4) POTENTIAL SHEAR WALL LOCATION
- 5 SINGLE POINT OF CONTACT ON FACADE OF EXISTING BUILDING. NEW STOREFRONT TO BE INSTALLED TO ALLOW FOR FUTURE POTENTIAL REMOVAL, IF NECESSARY
- (6) (N) WOOD PANELING & TRIM AT WALLS
- (7) (N) WOOD FLOOR

NOTE: SEE A5.11 - A6.07 FOR WINDOW & DOOR KEY PLANS, ELEVATIONS, LEGEND, & SCHEDULES









JACKSON PARK CLUBHOUSE RELOCATION & ADDITION





PROPOSED FLOOR PLAN 1/16" = 1'-0" 03/18/2022 A3.01



CAROLINA STREET








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION





SHEET NOTES


1 PATCH ROOF WHERE CHIMNEY REMOVAL OCCURRED


(N) MEMBRANE ROOF AT AREAS OF FLAT ROOF, COLOR TO MEET COOL ROOF REQ

(2) (N) COMPOSITION SHINGLE ROOF

PROPOSED ROOF PLAN 1/16" = 1'-0" 03/18/2022 A3.02

WEST ELEVATIONS - EXISTING & PROPOSED





PROPOSED - WEST ELEVATION
3/32" = 1'-0"







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

SHEET NOTES


- (1) (N) GLAZING. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) COMPOSITION SHINGLE ROOF
- (N) WOOD WINDOWS AND TRIM TO MATCH EXISTING
- (4) (N) ALUM FRAMED WINDOWS AT ADDITION
- 5) (N) HORIZONTAL MTL PANEL & LOUVER
- 6) (N) DOOR SYMPATHETIC TO HISTORIC CHARACTER
- 7) (N) ADDITION BEYOND
- 8) (N) GLAZED FOLDING DOOR TO CONNECT STAGE TO OUTDOOR THEATER
- (9) RENOVATED CLUBHOUSE BEYOND
- 10) BOARD FORM CONCRETE: BOARD FORM DIM. TO BE SIZED TO RELATE TO SPACE OF EXISTING FLUSH WOOD SIDING
- (11) PREP, PRIME, AND PAINT WOOD CLADDING & TRIM
- (12) PREP, PRIME, AND PAINT FLASHING, REPLACE AS REQ'D TO MATCH (E)
- (13) REHABILITATE (E) WINDOW FRAME, SASH, AND TRIM, REPLACE GLASS
- (14) PATCH / INFILL / REPAIR AREA & FINISH TO MATCH ADJ SURFACE TREATMENT
- 21) (E) CHIMNEY TO BE REMOVED
- (E) NON-HISTORIC HOLLOW MTL DOOR TO BE REPLACED
- (E) NON-ORIGINAL INFILL PANEL TO BE REMOVED
- (E) NON-ORIGINAL SECURITY GRATING TO BE REMOVED AT WINDOWS, TYP
- (E) WINDOW FRAME AND SASH TO BE RETAINED. TYP
- REMOVE PORTION OF (E) WALL FOR (N)




WEST ELEVATIONS -EXISTING & PROPOSED



NORTH ELEVATIONS - EXISTING & PROPOSED



1 EXISTING CLUBHOUSE (RELOCATED) - NORTH ELEVATION 3/32" = 1'-0"



2 PROPOSED - NORTH ELEVATION 3/32" = 1'-0"







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION


SHEET NOTES

- (N) GLAZING. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) COMPOSITION SHINGLE ROOF
- (N) WOOD WINDOWS AND TRIM TO MATCH EXISTING
- (4) (N) ALUM FRAMED WINDOWS AT ADDITION
- 5) (N) HORIZONTAL MTL PANEL & LOUVER
- 6) (N) DOOR SYMPATHETIC TO HISTORIC CHARACTER
- 7) (N) ADDITION BEYOND
- 8) (N) GLAZED FOLDING DOOR TO CONNECT STAGE TO OUTDOOR THEATER
- (9) RENOVATED CLUBHOUSE BEYOND
- 10) BOARD FORM CONCRETE: BOARD FORM DIM. TO BE SIZED TO RELATE TO SPACE OF EXISTING FLUSH WOOD SIDING
- (11) PREP, PRIME, AND PAINT WOOD CLADDING & TRIM
- (12) PREP, PRIME, AND PAINT FLASHING, REPLACE AS REQ'D TO MATCH (E)
- (13) REHABILITATE (E) WINDOW FRAME, SASH, AND TRIM, REPLACE GLASS
- 14) PATCH / INFILL / REPAIR AREA & FINISH TO MATCH ADJ SURFACE TREATMENT
- 21) (E) CHIMNEY TO BE REMOVED
- (E) NON-HISTORIC HOLLOW MTL DOOR TO BE REPLACED
- (E) NON-ORIGINAL INFILL PANEL TO BE REMOVED
- (E) NON-ORIGINAL SECURITY GRATING TO BE REMOVED AT WINDOWS, TYP
- (E) WINDOW FRAME AND SASH TO BE RETAINED. TYP
- 26) REMOVE PORTION OF (E) WALL FOR (N) DOOR




NORTH ELEVATIONS -EXISTING & PROPOSED

SOUTH ELEVATIONS - EXISTING & PROPOSED



EXISTING CLUBHOUSE (RELOCATED) - SOUTH ELEVATION



PROPOSED - SOUTH SECTION THROUGH NEW ADDITION
3/32" = 1'-0"









JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

SHEET NOTES

- (1) (N) GLAZING. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) COMPOSITION SHINGLE ROOF
- (N) WOOD WINDOWS AND TRIM TO MATCH EXISTING
- (4) (N) ALUM FRAMED WINDOWS AT ADDITION
- 5) (N) HORIZONTAL MTL PANEL & LOUVER
- (6) (N) DOOR SYMPATHETIC TO HISTORIC CHARACTER
- 7) (N) ADDITION BEYOND
- 8) (N) GLAZED FOLDING DOOR TO CONNECT STAGE TO OUTDOOR THEATER
- (9) RENOVATED CLUBHOUSE BEYOND
- 10) BOARD FORM CONCRETE: BOARD FORM DIM. TO BE SIZED TO RELATE TO SPACE OF EXISTING FLUSH WOOD SIDING
- 11) PREP, PRIME, AND PAINT WOOD CLADDING & TRIM
- (12) PREP, PRIME, AND PAINT FLASHING, REPLACE AS REQ'D TO MATCH (E)
- (13) REHABILITATE (E) WINDOW FRAME, SASH, AND TRIM, REPLACE GLASS
- (14) PATCH / INFILL / REPAIR AREA & FINISH TO MATCH ADJ SURFACE TREATMENT
- 21) (E) CHIMNEY TO BE REMOVED
- (E) NON-HISTORIC HOLLOW MTL DOOR TO BE REPLACED
- (E) NON-ORIGINAL INFILL PANEL TO BE REMOVED
- (E) NON-ORIGINAL SECURITY GRATING TO BE REMOVED AT WINDOWS, TYP
- (E) WINDOW FRAME AND SASH TO BE RETAINED. TYP
- REMOVE PORTION OF (E) WALL FOR (N)




SOUTH ELEVATIONS -EXISTING & PROPOSED



SOUTH ELEVATIONS - PROPOSED

NOTE:

SEE A4.03a FOR EXISTING SOUTH ELEVATION



PROPOSED - SOUTH ELEVATION
3/32" = 1'-0"








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

SHEET NOTES


- (1) (N) GLAZING. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) COMPOSITION SHINGLE ROOF
- (N) WOOD WINDOWS AND TRIM TO MATCH EXISTING
- (4) (N) ALUM FRAMED WINDOWS AT ADDITION
- 5) (N) HORIZONTAL MTL PANEL & LOUVER
- (N) DOOR SYMPATHETIC TO HISTORIC CHARACTER
- (7) (N) ADDITION BEYOND
- 8) (N) GLAZED FOLDING DOOR TO CONNECT STAGE TO OUTDOOR THEATER
- (9) RENOVATED CLUBHOUSE BEYOND
- 10 BOARD FORM CONCRETE: BOARD FORM DIM. TO BE SIZED TO RELATE TO SPACE OF EXISTING FLUSH WOOD SIDING
- 11) PREP, PRIME, AND PAINT WOOD CLADDING & TRIM
- (12) PREP, PRIME, AND PAINT FLASHING, REPLACE AS REQ'D TO MATCH (E)
- (13) REHABILITATE (E) WINDOW FRAME, SASH, AND TRIM, REPLACE GLASS
- (14) PATCH / INFILL / REPAIR AREA & FINISH TO MATCH ADJ SURFACE TREATMENT
- 21) (E) CHIMNEY TO BE REMOVED
- (E) NON-HISTORIC HOLLOW MTL DOOR TO BE REPLACED
- (E) NON-ORIGINAL INFILL PANEL TO BE REMOVED
- (E) NON-ORIGINAL SECURITY GRATING TO BE REMOVED AT WINDOWS, TYP
- (E) WINDOW FRAME AND SASH TO BE RETAINED, TYP
- 26) REMOVE PORTION OF (E) WALL FOR (N) DOOR




SOUTH ELEVATIONS - PROPOSED

As indicated 03/18/2022 A4.03b

EAST ELEVATIONS - EXISTING & PROPOSED



1 EXISTING CLUBHOUSE (RELOCATED) - EAST ELEVATION 3/32" = 1'-0"










JACKSON PARK CLUBHOUSE RELOCATION & ADDITION


SHEET NOTES

- (N) GLAZING. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) COMPOSITION SHINGLE ROOF
- (N) WOOD WINDOWS AND TRIM TO MATCH EXISTING
- (4) (N) ALUM FRAMED WINDOWS AT ADDITION
- 5) (N) HORIZONTAL MTL PANEL & LOUVER
- (6) (N) DOOR SYMPATHETIC TO HISTORIC CHARACTER
- (7) (N) ADDITION BEYOND
- (N) GLAZED FOLDING DOOR TO CONNECT STAGE TO OUTDOOR THEATER
- (9) RENOVATED CLUBHOUSE BEYOND
- (10) BOARD FORM CONCRETE: BOARD FORM DIM. TO BE SIZED TO RELATE TO SPACE OF EXISTING FLUSH WOOD SIDING
- (11) PREP, PRIME, AND PAINT WOOD CLADDING & TRIM
- (12) PREP, PRIME, AND PAINT FLASHING, REPLACE AS REQ'D TO MATCH (E)
- (13) REHABILITATE (E) WINDOW FRAME, SASH, AND TRIM, REPLACE GLASS
- (14) PATCH / INFILL / REPAIR AREA & FINISH TO MATCH ADJ SURFACE TREATMENT
- 21) (E) CHIMNEY TO BE REMOVED
- (E) NON-HISTORIC HOLLOW MTL DOOR TO BE REPLACED
- (E) NON-ORIGINAL INFILL PANEL TO BE REMOVED
- (24) (E) NON-ORIGINAL SECURITY GRATING TO BE REMOVED AT WINDOWS, TYP
- (E) WINDOW FRAME AND SASH TO BE RETAINED. TYP
 - REMOVE PORTION OF (E) WALL FOR (N)




As indicated

PROPOSED BUILDING SECTIONS



PROPOSED - SECTION
3/32" = 1'-0"



2 PROPOSED - SECTION 3/32" = 1'-0"

PLETCHIRBTUDIO







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION

SHEET NOTES

- (N) STOREFRONT SYSTEM. HORIZONTAL MULLIONS TO ALIGN WITH DESIGN ELEMENTS FROM CLUBHOUSE
- (2) (N) LOW STAGE
- (3) (N) ACCESSIBLE RAMP TO STAGE
- (4) (N) STAIRS TO STAGE
- (N) FOLDING GLAZED DOOR TO ACTIVATE OUTDOOR THEATER
- 6 (N) CLERESTORY WINDOW ABOVE (E) CLUBHOUSE WALL



EXISTING WINDOW & DOOR KEY PLAN - LEVEL 1



NOTE: SEE A1.01 & A1.02 FOR EXISTING FLOOR PLAN SHEET NOTES

LEGEND

- O DOOR TAG
- WINDOW TAG
- STOREFRONT TAG















EXISTING WINDOW & DOOR KEY PLAN - LEVEL 1

3/32" = 1'-0" 03/18/2022

A5.11

EXISTING WINDOW KEY PLAN - CLERESTORY



NOTE: SEE A1.01 & A1.02 FOR EXISTING FLOOR PLAN SHEET NOTES

LEGEND

- O DOOR TAG
- WINDOW TAG
- STOREFRONT TAG

















EXISTING WINDOW KEY PLAN -CLERESTORY 3/32" = 1'-0"
03/18/2022


A5.12


EXISTING WINDOW & DOOR KEY - ELEVATIONS















SOUTH ELEVATION 3/32" = 1'-0"








JACKSON PARK CLUBHOUSE **RELOCATION & ADDITION**



EXISTING WINDOW & DOOR KEY -**ELEVATIONS**

3/32" = 1'-0" 03/18/2022 A5.13










JACKSON PARK CLUBHOUSE RELOCATION & ADDITION






PROPOSED WINDOW & DOOR KEY PLAN - LEVEL 1

03/18/2022 A5.21

PROPOSED WINDOW KEY PLAN - CLERESTORY



























PROPOSED WINDOW KEY PLAN -CLERESTORY



PROPOSED WINDOW & DOOR KEY - ELEVATIONS



1 NORTH ELEVATION 3/32" = 1'-0"



2 WEST ELEVATION 3/32" = 1'-0"

LEGEND

O DOOR TAG

○ WINDOW TAG

STOREFRONT TAG







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION




PROPOSED WINDOW & DOOR KEY - ELEVATIONS

3/32" = 1'-0" 03/18/2022 **A5.23**

PROPOSED WINDOW & DOOR KEY - ELEVATIONS & SECTION





3/32" = 1'-0"

LEGEND

DOOR TAG

WINDOW TAG


STOREFRONT TAG







JACKSON PARK CLUBHOUSE **RELOCATION & ADDITION**



PROPOSED WINDOW & DOOR KEY -**ELEVATIONS &** -SECTION-

03/18/2022 A5.24

3/32" = 1'-0"

WINDOW SCHEDULE - EXISTING - LEVEL 1

MARK	TYPE	WIDTH	HEIGHT	WINDOW OPERATION	MATERIAL	EXISTING CONDITION	PROPOSED TREATMENT
400		41. 40!!	- OII	DOUBLE HING	144000	NO OLAGO FIREDOLAGO ATTAQUED TO QUITOIDE	
103	A		5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
104	A		5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
105	A		5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
106	Α		5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
107	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
108	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
111	Α		5' - 0"	DOUBLE HUNG	WOOD	NO GLASS; FIBERGLASS ATTACHED TO OUTSIDE	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
112	В		2' - 6"	HOPPER	WOOD	GLASS PAINTED RED	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
113	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	SOME PANES INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N), (N) LOWER SASH TO MATCH (E)
114	Α		5' - 0"	DOUBLE HUNG	WOOD	SOME PANES INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N), (N) LOWER SASH TO MATCH (E)
115	В	2' - 6"	2' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
116	В	2' - 6"	2' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
117	В	2' - 6"	2' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
118	С	2' - 6"	5' - 0"	DOUBLE HUNG	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
121	В	2' - 6"	2' - 6"	DOUBLE HUNG	WOOD		TO BE REMOVED & REPLACED WITH RECLAIMED SIDING
122	В	2' - 6"	2' - 6"	DOUBLE HUNG	WOOD	INFILLED W/ PLEXIGLASS	TO BE REMOVED & REPLACED WITH RECLAIMED SIDING
123	0	0' - 0"	0' - 0"	OPENING INFILLED W/ SOLID PANEL	WOOD		TO BE REMOVED & REPLACED WITH (N) WINDOWS TO MATCH HISTORIC WINDOWS
124	0	0' - 0"	0' - 0"	OPENING INFILLED W/ SOLID PANEL	WOOD		TO BE REMOVED & REPLACED WITH (N) OVERHEAD STAGE DOOR
125	0	0' - 0"	0' - 0"	OPENING INFILLED W/ SOLID PANEL	WOOD		TO BE REMOVED & REPLACED WITH (N) WINDOWS TO MATCH HISTORIC WINDOWS
126	В	2' - 6"	2' - 6"	DOUBLE HUNG	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
127	В	2' - 6"	2' - 6"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
128	F	1' - 4"	3' - 6"	CASEMENT	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
129	F	1' - 4"	3' - 6"	CASEMENT	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
130	F	1' - 4"	3' - 6"	CASEMENT	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
131	С	2' - 6"	5' - 0"	DOUBLE HUNG	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
132	В	2' - 6"	2' - 6"	HOPPER	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
133	В	2' - 6"	2' - 6"	HOPPER	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
134	В	2' - 6"	2' - 6"	HOPPER	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
135	В	2' - 6"	2' - 6"	HOPPER	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
136	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
137	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
138	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
139	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
140	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
141	Α	1' - 9"	5' - 0"	DOUBLE HUNG	WOOD	INFILLED W/ FIBERGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
142	F	1' - 4"	3' - 6"	CASEMENT	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)

NOTES:


- 1. WINDOW REHABILITATION WILL OCCUR AFTER RELOCATION OF CLUBHOUSE
- 2. WHERE FEASIBLE, RETAIN OPERATION OF ORIGINAL (E) WINDOW
- 3. NO INTERIOR WINDOWS ARE INCLUDED ON SCHEDULE ABOVE UNLESS PART OF ORIGINAL CLUBHOUSE
- 4. PRIME AND PAINT WOOD WINDOW TRIM, FRAMES, AND SASH, TYP.
- 5. REFER TO PHOTO ON 3/A0.13 FOR EXAMPLE OF FIBERGLASS INFILL AT (E) WINDOWS







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



WINDOW SCHEDULE - EXISTING - LEVEL 1

WINDOW SCHEDULE - EXISTING - CLERESTORY

MARK	TYPE	WIDTH	HEIGHT	WINDOW OPERATION	MATERIAL	EXISTING CONDITION	PROPOSED TREATMENT
1717 (1 (1 (WIBIII	11210111	WINDOW OF ERVITION	W/ CI EI C// CE	EXISTING GONETHON	THOI GOLD INLIMENT
201	E	1' - 10"	3' - 6"	HOPPER	WOOD	INFILLED W/ YELLOWED PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
202		1' - 10"	3' - 6"	HOPPER	WOOD	INFILLED W/ YELLOWED PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
203	E	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
204	E	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
205	Е	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ YELLOWED PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
206	E	1' - 10"	3' - 6"	FIXED	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
207	Е	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
208	Е	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
209	Е	1' - 10"	3' - 6"	HOPPER	WOOD	BROKEN & INFILLED W PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
210	E	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
211	E	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
212	E	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
213	E	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
214	E	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR; NO MUNTINS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
215	E	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
216	E	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
217	Е	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
218	E	1' - 10"	3' - 6"	FIXED	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
219	Е	1' - 10"	3' - 6"	HOPPER	WOOD		SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
220	Е	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
221	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
222	Е	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
223	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
224	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
225	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
226	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
227	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
228	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
229	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
230	E	1' - 10"	3' - 6"	UNABLE TO DETERMINE - 1	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
231	E	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
232	E	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ TARP ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
233		1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS & MISSING MUNTIN	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
234	Е	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
235	E	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
236	E	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
237	E	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
238	E	1' - 10"	3' - 6"	FIXED	WOOD	INFILLED W/ PLEXIGLASS	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
239	E	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)
240	E	1' - 10"	3' - 6"	HOPPER	WOOD	COVERED W/ PAPER ON INTERIOR	SASH & FRAME - REHABILITATE (E), GLASS - REPLACE W/ (N)

NOTES:


- 1. WINDOW REHABILITATION WILL OCCUR AFTER RELOCATION OF CLUBHOUSE
- 2. WHERE FEASIBLE, RETAIN OPERATION OF ORIGINAL (E) WINDOW
- 3. NO INTERIOR WINDOWS ARE INCLUDED ON SCHEDULE ABOVE UNLESS PART OF ORIGINAL CLUBHOUSE
- 4. PRIME AND PAINT WOOD WINDOW TRIM, FRAMES, AND SASH, TYP.
- 5. REFER TO PHOTO ON 3/A0.13 FOR EXAMPLE OF FIBERGLASS INFILL AT (E) WINDOWS







JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



WINDOW SCHEDULE -EXISTING -CLERESTORY

WINDOW SCHEDULE - NEW

MARK	TYPE	WIDTH	HEIGHT	WINDOW OPERATION	MATERIAL	NOTES
					1	
101	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
102	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
109	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
110	Α	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
149	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
150	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
154	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
155	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
156	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
157	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
158	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
159	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
160	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
161	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
162	F	1' - 10"	5' - 0"	DOUBLE HUNG	WOOD	
307	С	2' - 6"	4' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
308	С	2' - 6"	4' - 0"	DOUBLE HUNG	WOOD	REPLACE EXISTING INFILL PANEL, (N) WINDOW TO MATCH EXISTING OF SAME SIZE
	S4	SEE LEGEN	ND	STOREFRONT	ALUM/GLASS	
S1	S1	SEE LEGEN	ND	STOREFRONT	ALUM/GLASS	
S2	S2			STOREFRONT	ALUM/GLASS	
S3	S3			STOREFRONT	ALUM/GLASS	
S4	S4			STOREFRONT	ALUM/GLASS	
S5	S5	SEE LEGEND		STOREFRONT	ALUM/GLASS	
S6	S6	SEE LEGEND		STOREFRONT	ALUM/GLASS	
S7	S7	SEE LEGEND		STOREFRONT	ALUM/GLASS	
S8	S8	SEE LEGEND		STOREFRONT	ALUM/GLASS	

NOTES:


- 1. WINDOW REHABILITATION WILL OCCUR AFTER RELOCATION OF CLUBHOUSE
- 2. WHERE FEASIBLE, RETAIN OPERATION OF ORIGINAL (E) WINDOW
- 3. NO INTERIOR WINDOWS ARE INCLUDED ON SCHEDULE ABOVE UNLESS PART OF ORIGINAL CLUBHOUSE
- 4. PRIME AND PAINT WOOD WINDOW TRIM, FRAMES, AND SASH, TYP.
- 5. REFER TO PHOTO ON 3/A0.13 FOR EXAMPLE OF FIBERGLASS INFILL AT (E) WINDOWS








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION




WINDOW SCHEDULE -NEW

WINDOW LEGEND - EXISTING & NEW



1 WINDOW LEGEND DRAWINGS ABOVE DO NOT INDICATE WOOD TRIM
1/4" = 1'-0"




2 LOUVER LEGEND 3/16" = 1'-0"












WINDOW LEGEND -EXISTING & NEW As indicated 03/18/2022 A6.04

STOREFRONT LEGEND - NEW



EXTERIOR DOOR SCHEDULE - EXISTING & NEW

DOOR SCHEDULE - EXISTING						
MARK	TYPE	DESCRIPTION	MATERIAL	WIDTH	HEIGHT	NOTES
001	Р	OPENING INFILLED WITH MURAL	WOOD	5' - 0"	7' - 6"	TO BE REMOVED & REPLACED WITH NEW WINDOWS TO MATCH HISTORIC AESTHETIC
002	E1	DOUBLE EQUAL LEAF	MTL	6' - 0"	7' - 0"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC
003	Р	OPENING INFILLED WITH BLANK PANEL	WOOD	5' - 0"	7' - 6"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC
004	Р	OPENING INFILLED WITH BLANK PANEL	WOOD	3' - 0"	7' - 0"	TO BE REMOVED & REPLACED WITH RECLAIMED SIDING
005	Р	OPENING INFILLED WITH BLANK PANEL	WOOD	5' - 0"	7' - 6"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC
006	E3	SINGLE FLUSH	MTL	3' - 0"	7' - 0"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC
007	E2	DOUBLE UNEQUAL LEAF	MTL	5' - 4"	7' - 0"	TO BE REMOVED
800	E3	SINGLE FLUSH	MTL	3' - 0"	7' - 0"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC
009	Р	OPENING INFILLED WITH BLANK PANEL	WOOD	5' - 0"	7' - 6"	TO BE REMOVED & REPLACED WITH NEW DOOR TO MATCH HISTORIC AESTHETIC

אם כ								
DOOR SCHEDULE - NEW								
TYPE	DESCRIPTION	MATERIAL	WIDTH	HEIGHT	NOTES			
N1	DOUBLE EQUAL LEAF	PTD WOOD	6' - 0"	7' - 0"				
N3	DOUBLE UNEQUAL LEAF	PTD WOOD/GLASS	5' - 0"	7' - 0"	INTERIOR DOOR, PREVIOUSLY AN EXTERIOR CLUBHOUSE DOOR			
N2	SINGLE LEAF - SINGLE PANEL	PTD WOOD	3' - 0"	7' - 0"				
N2	SINGLE LEAF - SINGLE PANEL	PTD WOOD	3' - 0"	7' - 0"				
N6	FOLDING GLAZED STAGE DOOR	ALUM/GLASS	18' - 10"	9' - 0"	NANAWALL NW 640 FOLDING DOOR SYSTEM, LOW PROFILE SADDLE SILL-INWARD OPENING, TEMPERED GLASS, DARK BRONZE FINISH			
N3	DOUBLE UNEQUAL LEAF	PTD WOOD	6' - 0"	7' - 0"				
N4	DOUBLE STOREFRONT	ALUM/GLASS	6' - 0"	7' - 3 1/2"				
N4	DOUBLE STOREFRONT	ALUM/GLASS	3' - 0"	. 7' - 3 1/2"				
N5	SINGLE STOREFRONT	ALUM/GLASS	3' - 0"	. 7' - 3 1/2"				
N5	SINGLE STOREFRONT	ALUM/GLASS	2' - 9 1/2"	7' - 3 1/2"				
111111111111111111111111111111111111111	TYPE 11 13 12 12 16 13 14 14 15	TYPE DESCRIPTION 11 DOUBLE EQUAL LEAF 13 DOUBLE UNEQUAL LEAF 14 SINGLE LEAF - SINGLE PANEL 15 SINGLE LEAF - SINGLE PANEL 16 FOLDING GLAZED STAGE DOOR 17 DOUBLE UNEQUAL LEAF 18 DOUBLE STOREFRONT 18 SINGLE STOREFRONT 18 SINGLE STOREFRONT	TYPE DESCRIPTION MATERIAL 11 DOUBLE EQUAL LEAF 13 DOUBLE UNEQUAL LEAF 14 PTD WOOD 15 SINGLE LEAF - SINGLE PANEL 16 FOLDING GLAZED STAGE DOOR 17 DOUBLE UNEQUAL LEAF 18 DOUBLE UNEQUAL LEAF 18 DOUBLE STOREFRONT 18 DOUBLE STOREFRONT 18 ALUM/GLASS 19 SINGLE STOREFRONT 19 ALUM/GLASS 10 SINGLE STOREFRONT 10 ALUM/GLASS 11 SINGLE STOREFRONT 11 ALUM/GLASS 12 SINGLE STOREFRONT 12 ALUM/GLASS 15 SINGLE STOREFRONT 16 ALUM/GLASS 16 SINGLE STOREFRONT 17 ALUM/GLASS 17 DOUBLE STOREFRONT 18 ALUM/GLASS 18 SINGLE STOREFRONT 18 ALUM/GLASS 19 SINGLE STOREFRONT 18 ALUM/GLASS	TYPE DESCRIPTION MATERIAL WIDTH N1 DOUBLE EQUAL LEAF PTD WOOD 6' - 0" N3 DOUBLE UNEQUAL LEAF PTD WOOD/GLASS N2 SINGLE LEAF - SINGLE PANEL PTD WOOD 3' - 0" N2 SINGLE LEAF - SINGLE PANEL PTD WOOD 3' - 0" N6 FOLDING GLAZED STAGE DOOR ALUM/GLASS 18' - 10" N3 DOUBLE UNEQUAL LEAF PTD WOOD 6' - 0" N4 DOUBLE STOREFRONT ALUM/GLASS 3' - 0" N5 SINGLE STOREFRONT ALUM/GLASS 3' - 0"	TYPE DESCRIPTION MATERIAL WIDTH HEIGHT N1 DOUBLE EQUAL LEAF PTD WOOD 6' - 0" 7' - 0" N3 DOUBLE UNEQUAL LEAF PTD WOOD 5' - 0" 7' - 0" N2 SINGLE LEAF - SINGLE PANEL PTD WOOD 3' - 0" 7' - 0" N2 SINGLE LEAF - SINGLE PANEL PTD WOOD 3' - 0" 7' - 0" N6 FOLDING GLAZED STAGE DOOR ALUM/GLASS 18' - 10" 9' - 0" N3 DOUBLE UNEQUAL LEAF PTD WOOD 6' - 0" 7' - 0" N4 DOUBLE STOREFRONT ALUM/GLASS 6' - 0" 7' - 3 1/2" N4 DOUBLE STOREFRONT ALUM/GLASS 3' - 0" . 7' - 3 1/2" N5 SINGLE STOREFRONT ALUM/GLASS 3' - 0" . 7' - 3 1/2"			

NOTES


1. NO INTERIOR DOORS ARE INCLUDED ON DOOR SCHEDULE WITH THE EXCEPTION OF DOOR 102












EXTERIOR DOOR SCHEDULE - EXISTING & NEW 03/18/2022 A6.06

EXTERIOR DOOR LEGEND - EXISTING & NEW








LEAF - SINGLE PANEL



SINLE PANEL

LEAF - SINGLE PANEL





EXTERIOR DOOR LEGEND - EXISTING & NEW

GLAZED FOLDING DOOR PRECEDENT

REFERENCE PROJECT - Palo Alto Children's Library Renovation

The Palo Alto Children's Library Renovation by Architecture Resources Group (ARG) incorporated a bronze Nanawall folder glazed door into a historic 1939 Spanish Colonial Revival children's library. The programmatic function, scale and historic integration of the door of this project illustrate the approach towards the new Stage Door at the renovated Jackson Park Clubhouse.





1 NANAWALL FOLDING GLAZED DOOR EXTERIOR

2 NANAWALL FOLDING GLAZED DOOR INTERIOR


JACKSON PARK CLUBHOUSE

RELOCATION & ADDITION











1/8" = 1'-0"

03/18/2022

GLAZED FOLDING DOOR



2 HEAD AT STAGE DOOR



Typical Simulated Divided Lites Muntin with Spacer Bar

3 DIVIDED LITE MUNTIN AT STAGE DOOR N.T.S.

NOTE:


STAGE DOOR DETAILS ARE PROVIDED BY NANAWALL, SHOP DRAWINGS WILL BE PROVIDED PRIOR TO FABRICATION








JACKSON PARK CLUBHOUSE RELOCATION & ADDITION



GLAZED FOLDING DOOR DETAILS

PERSPECTIVE VIEW FROM NORTHWEST















PERSPECTIVE VIEW FROM NORTHWEST

PERSPECTIVE VIEW FROM NORTHWEST















PERSPECTIVE VIEW FROM NORTHWEST

03/18/2022 A7.02

PERSPECTIVE VIEW FROM WEST
















PERSPECTIVE VIEW FROM WEST

PERSPECTIVE VIEW FROM SOUTHWEST















PERSPECTIVE VIEW
FROM SOUTHWEST

PERSPECTIVE VIEW FROM SOUTH
















PERSPECTIVE VIEW FROM SOUTH

PERSPECTIVE VIEW FROM SOUTHEAST
















PERSPECTIVE VIEW FROM SOUTHEAST

PERSPECTIVE VIEW FROM EAST
















PERSPECTIVE VIEW FROM EAST

PERSPECTIVE VIEW FROM NORTHEAST
















PERSPECTIVE VIEW FROM NORTHEAST

PERSPECTIVE VIEW FROM NORTH
















PERSPECTIVE VIEW FROM NORTH